



Engineers Details

Domestic/Landlord Gas Safety Record

Installation Details

18 Barchester 2023

Client Details

Certificate No:

Certificate Reference

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Trading Title		Blue Frog Plumbing and Heating LTD						allation lress	Freddie North							Freddie North					
Address		60 West Drayton Park Avenue						1699	18					Addres	18						
		West Drayton						Barchester Close					Barch	nester Close							
		Middlesex						Cowley						Cowl	ey						
		Post Code: UB77QB							Post Code: UB8 2JY						Post Code: UB82JY				Y		
Gas Safe No:		508237 Telep			ohone No: 07827974485		Telephone No		o: +447435967433				Telephone No: +44743			967433					
Appliance Details							Inspection Details														
	Locatio	Location		псе Туре	Make	Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/NO) (NO - Vaust Inspector)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)		
1	Kitche	Kitchen		neating boiler	Worcester Bosch	18 Ri	9.2	9.8		82ppm	YES	RS	YES	YES	YES	YES	PASS	YES	YES		
2	2																				
3																					
4																					
5																					
Faults/Notes							Remedial Work Taken									Warning Notice Fixed					
1																			NA		
2																					
3																					
4																					
5																					
Acceptible: YES Gas rightness Satisfactory. NA									Signatures Report Issued By: Gas ID Number:										4929590		
Contractallation Dinescont Visual Inspection Catiofactors																		Wed-10-05-2023			
Num	nber of Applia	ances Te	sted:	1	Equipotential I	Bonding: YES	Re	eport Received By:													
	T INSPECTION	ION DUE ON Fri-		Fri-10-05	ri-10-05-2024 Installation Pass: YES			. –					Date:	Wed-10-05-2023							
CO /	Alarm fitted &	& working	g? [YES Sr	moke alarm fitted &	k working? YES		Fo	or appliances	This Gas Sa	fety Report way	as created by	Gas Checker So	oftware all rights	reserved w	ww.gaschecker.co.	uk	alv			