



Domestic/Landlord Gas Safety Record

(Integrity, Construction and Lining) has been carried out.

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues

Certificate Reference

31 Barchester Close 2023

Certificate No:

Engineers Details							llation C	Details			Client Details								
Trading Title		Blue Frog Plumbing and Heating LTD					Installation Address		Freddy North					Fredd	Freddy North				
Address		60 West Drayton Park Avenue					ress	31				Address	Nexus	Nexus West London					
		West Drayton					Barcheste						31 Ba	31 Barchester Close					
		Middlesex						Cowley						Cowley					
		Post Code: UB77QB						Post Code: UB82JY							Post Code: UB82JY			Y	
Gas	s Safe No:	508237 Telephone No: 07827974485					lephone No: +447435967433					Telephone No: +447435967			7433				
Appliance Details						_	Inspection Details												
	Locatio	on	Appliance Type	Make	Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/NO) (NO = Visual Inspector)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Landi	ng	Combi boiler	Worcester Bosch	25i	9.2	9.3	19mb mb	80ppm	YES	RS	YES	YES	YES	YES	PASS	YES	YES	
2																			
3																			
4																			
\vdash																			
5 Faults/Notes							Remedial Work Taken											Warning Notice Fixed	
1																	Warming House Fixed		
2	2																		
3																			
4							+												
5																			
Emerganou Control Valvo								atures Cas ID Number:											
Accessible: YES Gas rightness satisfactory. YES Repo								ort Issued By:									4929590		
Gas Installation Pipework Visual Inspection Satisfactory: YES Name									e: Adam Christian Stone Signed: Date:								Sun-22-10-2023		
Nun	nber of Appli	ances Te	sted: 1	oort Re	rt Received By:								·						
NEXT INSPECTION DUE ON OR BEFORE: Tue-22-10-2024 Installation Pass: YES						Nai	me: N	Not Present Signed: Date:							Sun-22-10-2023				
СО	Alarm fitted a	& working	g? YES Si	moke alarm fitted &	working? YES	or appliances	This Gas Sa	fety Report way	as created by	y Gas Checker S	oftware all rights re e' response is base	served ww	vw.gaschecker.co.	uk ous defects c	only				