



# Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.  
This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

20 Barchester Close 2025

Certificate No:

## Engineers Details

Trading Title Blue Frog Plumbing and Heating LTD

Address 60 West Drayton Park Avenue  
West Drayton  
Middlesex

Post Code: UB77QB

Gas Safe No: 508237

Telephone No: 07827974485

## Installation Details

Installation Address

Freddie North  
20  
Barchester Close  
Cowley

Post Code: UB82JY

Telephone No: +447435967433

## Client Details

Client Address  
Freddie North  
20  
Barchester Close  
Cowley

Post Code: UB82JY

Telephone No: +447435967433

## Appliance Details

|   | Location | Appliance Type         | Make            | Model | Combustion LOW<br>(CO2% or CO/CO2 ratio) | Combustion HIGH<br>(CO2% or CO/CO2 ratio) | Heat Input<br>or<br>Operating Pressure<br>(kW)<br>(mbar) | CO Reading (ppm) | Appliance<br>Inspected<br>(YES/NO/NA/0)<br>(0/0 is final inspection only) | Flue Type<br>(OF/RS/FL) | Landlords<br>Appliance<br>(YES/NO/NA) | Safety Device(s)<br>Correct<br>Operation<br>(YES/NO/NA) | Ventilation<br>Provision<br>Satisfactory<br>(YES/NO/NA) | Visual Condition<br>Of Flue and<br>Termination<br>Satisfactory<br>(YES/NO/NA) | Flue Performance<br>Test<br>(PASS/FAIL/NA) | Appliance<br>Serviced<br>(YES/NO/NA) | Appliance<br>Safe To Use<br>(YES/NO) |
|---|----------|------------------------|-----------------|-------|--|---|--|------------------|---|-------------------------|---------------------------------------|---|---|---|--|--------------------------------------|--------------------------------------|
| 1 | Kitchen  | Central heating boiler | Worcester Bosch | 18 Ri | 9.0                                      | 9.2                                       | 20mb mb  | 80               | YES   | RS                      | YES                                   | YES   | YES   | YES   | PASS                                       | YES                                  | YES                                  |
| 2 |          |                        |                 |       |  |   |  |                  |   |                         |                                       |   |   |   |  |                                      |                                      |
| 3 |          |                        |                 |       |  |   |  |                  |   |                         |                                       |   |   |   |  |                                      |                                      |
| 4 |          |                        |                 |       |  |   |  |                  |   |                         |                                       |   |   |   |  |                                      |                                      |
| 5 |          |                        |                 |       |  |   |  |                  |   |                         |                                       |   |   |   |  |                                      |                                      |

## Faults/Notes

## Remedial Work Taken

## Warning Notice Fixed

|   |  |  |
|---|--|--|
| 1 |  |  |
| 2 |  |  |
| 3 |  |  |
| 4 |  |  |
| 5 |  |  |

Emergency Control Valve  
Accessible:

YES

Gas Tightness Satisfactory:

NA

## Signatures

Gas ID Number: 4929590

Gas Installation Pipework Visual Inspection Satisfactory:

YES

Report Issued By:

Number of Appliances Tested:

1

Equipotential Bonding:

YES

NEXT INSPECTION DUE ON  
OR BEFORE:

Sun-18-10-2026

Installation Pass:

YES

CO Alarm fitted & working?

YES

Smoke alarm fitted & working?

YES

Signed:

Date: Sat-11-10-2025

Report Received By:

Signed:

Date: Sat-11-10-2025